Since the start of 2014 the crane has been very seldom used just a couple of running hour per month.

We have performed regular maintenance during this time until the storm accident 2017-01. (The crane was pushed by storm winds twice that day)

You find some damage-pictures in the folder.

Good to know:

The crane lack a proper function on the whole high voltage supply chain.

No high voltage-cable

No pick up wagon between quay and crane

No working high voltage cable-reel

No driver seat in the cabin

Classification: Public